




September 4, 2007

## BCI Burke Announces Recall to Repair Swing Sets

**Name of Product:** In cooperation with the U.S. Consumer Product Safety Commission (CPSC), the BCI Burke Company, of Fond du Lac, WI, is recalling about 664 playground single post swing sets for retrofit. The product affected is the Top Beam of a 2-3/8" Single Post Swing Set (550-0033) and Added Bays (550-0035) with belt or bucket seats. The swings are made with a 2-3/8" diameter top beam that is welded to a formed plate on each end to attach to the upright post. These were shipped between January 1, 2000 and August 3, 2007. Consumers should stop using the product immediately unless otherwise instructed.



**Hazard:** The connection of the swing set top beam to the formed end plate of the top beam can break. If this happens, the swing set top beam can collapse causing children on the swings to fall and be injured by the falling top rail.

**Incidents:** There has been one report of a child being injured which included bruises.

**Remedy:** Due to this recall, please prevent further use of the swing set by removing the existing swings from the top beam immediately. These swings can be re-installed AFTER the retrofit kit is received and installed in conjunction with the current beam. BCI Burke will contact the owners directly by mail and provide a retrofit kit.

**Consumer Contact:** Contact BCI Burke customer service toll-free at (800) 356-2070 between 8 a.m. and 4 p.m. CST Monday through Friday, or visit our Website at [www.bciburke.com](http://www.bciburke.com)

**BCI Burke Company, LLC**

660 Van Dyne Road • P.O. Box 549 • Fond du Lac, WI 54936-0549 • (920) 921-9220 • (920) 921-9566 •  
[www.bciburke.com](http://www.bciburke.com)

**Burke...Your Partner in Play™**